

5081358



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200

D3370-041**Job Sheet 179236****Part No:** D3370-041**Job Qty:** 1 ea**Part Name:** Tail Rotor Pedal Lock**Part Weight:** 0 lbs**Status:** Scheduled**Priority:** Medium**Job Created:** 6/14/18**Job Tracking No:** RA171**Due Date:** 6/28/18**Created By:** Michelle Gagnon-Donovan**Type:** Return**Description:****Note:** DWG REV C**Ship Via:****Bill of Materials****Job Routing**

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup hrs	Run Hrs	Workcenter / Supplier	Lead Time	
90	Start up Operation	1 Ea	6/28/18	6/28/18	0.00	0.00	Start Up Stores/Pkg-2		met 18.06.14
110	Small Fab	1 pcs	6/28/18	6/28/18	0.00	0.36	Small Fab-3		SAG DAS 38
120	QC	1 pcs	6/28/18	6/28/18	0.00	0.00	QC5		38
130	Packaging	1 pcs	6/28/18	6/28/18	0.00	0.00	Packaging3-1		SH97 OCT 23 2018 6 9-89
140	QC21-SA	1 Ea	6/28/18	6/28/18	0.00	0.00	QC21		DAS 21 9-89 OCT 23 2018

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
D3370-041	Tail Rotor Pedal Lock	1 Ea (1 ea)	90-Start up Operation	S045000

Job Allocations

Operation	Component Part	Required	Inventory	Allocated
90-Start up Operation	D3370-041	1	1	1

Allocated Container Detail

Qty	Container No	Location	Init
1	S045000	conditional release	_____

Part Specifications

Specifications could not be found.

Plex 6/14/18 3:37 PM Dart.Gagnon.Michelle

DART
AEROSPACE

Hawkesbury, ON K6A 1K7
CANADA
TEL.: 1 613 632-5200
Email: sales@dartaero.com
www.dartaerospace.com

Container No: S081358



Part: D3370-C41

Job No: 179236

Serial No/Batch: S081358

Revision:

Inspector:

Exp Date:

Instructions: Various STC's

Date: 10/22/18

8103
98

8103

Inspection Sheet Complete **RA171**

Customer QA Ref #

0

Part Number	Batch / Serial #	Quantity	Part Complete	Rev/CHG Current	New Paperwork	New Labels	Disposition	Work order #	Work order instructions
D3370-041	N/A	#VALUE!	☐ Yes	☐ Yes	☐ Yes	☐ Yes	DAMAGED/REPAIRABLE	S045000	Customer returning because locking mechanism does not work. Scrap and replace cam lock assembly D3373-5. Inspect to make sure locking mechanism works well. Return in stock. I.D. with new batch at Rev D. Please note that batch number is unknown.
0		#VALUE!	☐ Yes	☐ Yes	☐ Yes	☐ Yes			
0		#VALUE!	☐ Yes	☐ Yes	☐ Yes	☐ Yes			
0		#VALUE!	☐ Yes	☐ Yes	☐ Yes	☐ Yes			
0		#VALUE!	☐ Yes	☐ Yes	☐ Yes	☐ Yes			
0		#VALUE!	☐ Yes	☐ Yes	☐ Yes	☐ Yes			

QC Approval: P.D. _____

Date: 28-Feb-18 _____